


**Reception Room**

*Photo Survey | First Floor*






**Bedroom**


Photo Survey | First Floor







### Bathroom

Photo Survey | First Floor



Existing Second Floor Plan | 13 Belsize Crescent







**Second Floor Hallway**

*Photo Survey | Second Floor*






**Reception Room**

*Photo Survey | Second Floor*






**Kitchen**

Photo Survey | Second Floor






**Bathroom**

Photo Survey | Second Floor










**Hallway**  
*Photo Survey | Third Floor*





Bedroom






**Bathroom**


Photo Survey | Third Floor





**Study**  
*Photo Survey | Third Floor*






Bedroom

Photo Survey | Third Floor







Roof

Photo Survey | Roof





Rear External

Photo Survey | Ground Floor