




## Network Building Contamination Monitoring Report LIVE DOCUMENT

This document sets out testing we've taken to date, the location the samples were taken from and the results.

We are currently carrying out the bulk excavation on the project and will be regularly testing the soil as we go. This document will be a live document until such time as the bulk excavation is completed in June.

## Soil Testing Mark Up





## **Results**

See below summary of results and references below:

## Sample 1

We took the first sample of soil when we removed the original ground floor slab during some trial hole works before the piling operation. The samples were taken to from existing ground to above clay level.

Sample 1	Date Sample Take	Results of Sample	Positive or Negative	Comments
DC12430-2A	01.12.22	05.12.23	Negative	
DC12430-3A	01.12.22	05.12.23	Negative	
DC12430-6A	01.12.22	05.12.23	Negative	
DC12430-7A	01.12.22	05.12.23	Negative	
DC12430-8A	01.12.22	05.12.23	Negative	
DC12430-9A	01.12.22	05.12.23	Negative	
DC12430-10A	01.12.22	05.12.23	Negative	
DC12430-11A	01.12.22	05.12.23	Negative	