



Monitoring Details

Provider Name:	My Home Needs Ltd	Monitoring Interval:	2 Monthly
Instruction Date:	26/10/2022	Number of Visits:	7
Reading Date:	31/03/2023	Visits Completed:	3
Date of Issue:	31/03/2023	Visits Outstanding:	4

Client Details


Client:	Crawfords	Engineer / Handler:	Joannou J
Job Reference:	[REDACTED]		

Monitored Address

Occupier:

Address: 10 Park Village East, London,
NW1 7PX

Site Plan



Level Readings (Displayed in metres)

Visits	2	3	4	5	6	7	8	9
04/11/2022	8.8269	11.1307	11.1226	9.9099	9.9284	9.9683	10.0163	10.0000
01/02/2023	8.8266	11.1306	11.1221	9.9120	9.9293	9.9683	10.0160	10.0000
31/03/2023	8.8268	11.1303	11.1222	9.9129	9.9299	9.9684	10.0162	10.0000

Visits	📌 DATUM
04/11/2022	10.0000
01/02/2023	10.0000
31/03/2023	10.0000


DATUM: Datum is level station 1 for the front and level station 9 for the rear, it has an assumed value of 10,0000m. No suitable remote datum available. If this is not suitable please advise if a deep datum is required.

Level Readings Difference (Displayed in millimetres)

Visits	2	3	4	5	6	7	8	9
04/11/2022	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
01/02/2023	-0.30 ↓	-0.10 ↓	-0.50 ↓	2.10 ↑	0.90 ↑	0.00 =	-0.30 ↓	0.00 =
31/03/2023	0.20 ↑	-0.30 ↓	0.10 ↑	0.90 ↑	0.60 ↑	0.10 ↑	0.20 ↑	0.00 =


Visits	📌 DATUM
04/11/2022	N/A
01/02/2023	0.00 =
31/03/2023	0.00 =

Relative Movement (Relative Survey, for illustration purposes only)



■ Baseline
■ Visit 1 (04/11/2022) ■ Visit 2 (01/02/2023) ■ Visit 3 (31/03/2023)

Level Readings Chart





Homeowner Notes

Visit	Homeowner Notes
04/11/2022	No concerns raised.
01/02/2023	No concerns raised.
31/03/2023	No concerns raised.