


EXISTING SITE CONDITION SHOWING RECESSED ENTRANCE AREA TO SHOPFRONT ONTO HAMPSTEAD HIGH STREET

EXAMPLES OF PRECEDENT SECURITY ENTRANCE GATES TO PERIOD SHOPFRONT RECESSED ENTRANCES (FROM OTHER UK BOROUGH CONSERVATION AREAS)



EXISTING SITE CONDITION SHOWING PANELLED TIMBER FASCIAS TO WINDOWS ONTO PERRIN'S COURT