











For illustration purposes. All dimensions to be reconfirmed by contractor on site prior to any construction

Flat 3, 101 Greencroft : London, NW6 3PG

Drawing No:

250 : Front Elevation E&P



Rotten timber framed sash windows at first floor with cracked single glazing to be replaced with new timber frame sash windows with double glazing frames to match existing.

ISSUED : 06.06.2023

THE KLASSNIK CORPORATION info@klassnik.com www.klassnik.com