T2
Pride of India
C2

T4
Ash
C2

T5
Cherry
U

T3
Dead Viburnum
U

T1
Ash
B2

T17
Plane
C2

G6
Lime
A2

G7
Buddleia

H8
Cypress
C2

H8
Cypress
C2

H8
Cypress
C2

T9
Dead Chestnut
U

Japanese Knotweed

T14
Oak
C2

T15
Laurel

T16
Ash+Elder
C2

T18
Oak
U

T12
Ash
C2

T13
Yew
C2

Monstera 3m

G10
Sycamore
C2

G11
Lime
A2

Section of wall to be replaced

No access

CHAMBER EXTENSION (JOIN WITH FIT MARKS)

FIT MARK A

FIT MARK B

30m

LYNDHURST GARDENS

NOTE:
This survey is of a preliminary nature. The trees were inspected from the ground only on the basis of the Visual Tree Assessment method. No samples were taken for analysis. No decay detection equipment was employed. The survey does not cover the arrangements that may be required in connection with the laying or removal of underground services.

Branch spread in metres is taken at the four cardinal points to derive an accurate representation of the crown.

Root Protection Areas (RPA) are derived from stem diameter measured at 1.5 m above adjacent ground level (taken on sloping ground on the upslope side of the tree base).


Landmark Trees
20 Broadwick Street, London, W1F 8HT
Tel: 0207 851 4544 Mobile: 07812 989928
e-mail: info@landmarktrees.co.uk Web: www.landmarktrees.co.uk


Site: 17 Lyndhurst | 1:100@ A1

Drawing Title: Arboricultural Impacts Assessment | November 2022

Key:

- Category A High Quality
- Category B Moderate Quality
- Category C Low Quality
- Category U Trees Unsuitable for Retention

Category, Crown Spread, Root Protection Area, Tree Number, Species, Category (T3 Beech B2)

Tree Position Approximate (not shown on original survey)

N

5m 10m