



EMAIL info@thiss.studio  
TEL +44 (0) 203 848 4370  
INSTAGRAM thiss.studio

29 Wadeson Street,  
London  
E29DR

14 Well Road, NW3 1LH

# Rear Garden Photos

2023/3262/P



View towards the existing retaining wall and side passage.



The Existing Fence is rotting and has collapsed. It has been temporarily propped to keep it upright.



View towards the rear wall of the garden.

The new boundary fence between N14 and N13 will be replaced to match the existing fence at the rear boundary shared with N21 Well Walk.