

# CRACK MONITORING

## for Subsidence Management Services

**29 Edis Street, London, NW1 8LE**

Client: Subsidence Management Services

Client Contact: Robbie Taylor

Claim Number:

Client Reference:

Policy Holder:

Report Date: 12 September 2023

Our Ref:

## Crack Monitoring Readings

The following table shows the reading levels of the Crack Monitoring Stations.

| Date   | A=B (H) | B=C (D) | A=C (V)(C) | Crack Width |
|--|---------|---------|------------|-------------|
| <b>C1 - Landing (Front ground floor) ceiling near WC</b> |         |         |            |             |
| 15 February 2023   | 66.12   | 89.06   | 65.51      | 1.30 - 2.00 |
| 28 April 2023  | 65.91   | 88.91   | 65.45      | 1.60 - 1.70 |
| 12 July 2023   | 66.33   | 89.27   | 65.46      | 2.30 - 2.30 |
| 8 September 2023   | 67.30   | 89.97   | 65.45      | 4.40        |

## Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.

