

REVISION	DATE	REASON
PR1	30.06.23	REVIEW
PR2	06.10.23	PLANNING ISSUE
PR3	23.10.23	PLANNING ISSUE

Amended Items in Yellow

638 - 28 CHALCOT SQUARE

SH-10 Proposed Window Schedule

NOTE: CLIENT TO REVIEW AND APPROVE ALL FINISHES

WINDOW SCHEDULE				
Ref	Description	Manufacturer & Ref.	Visual	Notes
NOTE: 1. Colour code: green = new window 2. All works subject to planning approval 3. Allow for sash windows to be re-corded where necessary				
LOWER GROUND FLOOR				
WLG-01	Front elevation - window to teapoint	Existing window to be removed, opening to be made wider and new door put in place, ref elevations, SE to consult on structural alterations		
WLG-02	Rear elevation - bedroom window	Existing window to be made good and repainted as per schedule		
WLG-03	Rear elevation - bedroom window	Existing window to be made good and repainted as per schedule		
WLG-04	New sash window to front lightwell	New window in place of existing door opening, ref. elevations, to be double glazed		
GROUND FLOOR				
WG-01	Front elevation - window to dining room	Existing window to be made good and repainted as per schedule		Internal window shutter to be retained
WG-02	Rear elevation - window to kitchen	Existing window to be made good and repainted as per schedule		
WG-03	Rear elevation - window to WC	Existing window to be made good and repainted as per schedule		
FIRST FLOOR				
W1-01	Front elevation - window to living room	Existing window to be made good and repainted as per schedule		
W1-02	Front elevation - window to living room	Existing window to be made good and repainted as per schedule		
W1-03	Front elevation - window to living room	Existing window to be made good and repainted as per schedule		
W1-04	Rear elevation - window to living room	Existing window to be made good and repainted as per schedule		
W1-05	Rear elevation - window to study	Existing window to be made good and repainted as per schedule		
SECOND FLOOR				
W2-01	Front elevation - window to bedroom	Existing window to be made good and repainted as per schedule		

W2-02	Front elevation - window to bedroom	Existing window to be made good and repainted as per schedule		
W2-03	Front elevation - window to bedroom	Existing window to be made good and repainted as per schedule		
W2-04	Rear elevation - window to bathroom	Existing window to be made good and repainted as per schedule - internal waterproof privacy shutters to be added, spec. TBC		
W2-05	Rear elevation - window to walk in wardrobe	Existing window to be made good and repainted as per schedule		
W2-06	Rear elevation - window to stairwell	Existing window to be made good and repainted as per schedule		
THIRD FLOOR				
W3-01	Front elevation - window to single bedroom	Existing window to be made good and repainted as per schedule		
W3-02	Front elevation - window to double bedroom	Existing window to be made good and repainted as per schedule		
W3-03	Front elevation - window to double bedroom	Existing window to be made good and repainted as per schedule		
W3-04	Rear elevation - window to single bedroom	Existing window to be removed and replaced as per elevation		
W3-05	Rear elevation - window to bathroom	Existing window to be removed and replaced as per elevation - internal waterproof privacy shutters to be added, spec. TBC		
W3-06	Rear elevation - window to stairwell	Existing window to be made good and repainted as per schedule		
W3-06/2	Rear elevation - window to stairwell	New conservation roof light in new structural opening, ref. rear elevation / section		
THIRD FLOOR				
W4-01	Existing skylight to be removed and replaced as per proposal	New conservation roof light, existing structural opening to be modified, ref. rear elevation / plans		
W4-02	Additional skylight added	New conservation roof light in new structural opening, ref. rear elevation / plans		