

SITE PHOTOGRAPHS

Changes to the shopfront

Unit 1
1-11a Swain's Lane
London N6 6AG

February 2024
TIA-TR4-DOC-03



Photo 1 - Shopfront



Photo 2 - Internal view towards the main entrance, with ventilation intake dropping lower than the shopfront




Photo 3 - Internal view towards the other side of the shopfront, with ventilation exhaust 'disappearing' within the building build-up zone



Photo 4 - Main entrance close-up, with ventilation intake grille dropping lower than the shopfront, above the main doors