



1 - Front Elevation




2 - Side Elevation

Existing solid doors removed and replaced with side hung casement windows in style to match existing windows

Existing doors removed and replaced with new timber door set comprising of double door and fixed side light



3 - Basement Elevation



4 - Side Elevation

