

Swiss Cottage Library
CPT Project – Ground Floor Photos



1: Existing interview room door – to be renewed in widened opening



2: Interview room door – plastic finger plate & kick plate

Swiss Cottage Library
CPT Project – Ground Floor Photos



3: Existing DDA WC door – new CPT room door to match this as closely as possible



4: DDA WC door – new CPT room door to match this

Swiss Cottage Library
CPT Project – Ground Floor Photos



5: Interview room from room door




6: Interview room facing room door

Swiss Cottage Library
CPT Project – Ground Floor Photos



7: Typical Interview room skirting to be removed



8: Interview room vinyl flooring to be renewed

Swiss Cottage Library
CPT Project – Ground Floor Photos