




Provider Details		Client Details		Risk Address	
Name:	MHN Ltd	Insurance Co.:		Occupier:	
		Client Name:	Sedgwick	Address:	13 Weech Road
	09/02/2024	Contact:		Address:	London
Date of Issue:		Email:		Town:	
		Client Ref:		County:	
Monitoring Details		Address:	2 The Boulevard	Post Code:	NW6 1DL
Instruction Date:	19/8/20	Address:	City West One Office Park	Tel Home:	
First Reading Date:	27/08/2020	Address:	Gelderd Road	Tel Work:	
Maximum No Visits:	UFN	Town:	Leeds	Mobile:	
Anticipated Expiry Date:	Dec 2023	County:	West Yorkshire	Other:	
Monitoring Int:	6 Weekly	Post Code:	LS12 6NY	Other:	

[illegible]

09/02/2024

- It was not possible to install all stations within a common brickcourse. Therefore initial readings cannot be interpreted as Distortion Data.
- Readings have been made relative to level station 1. It has an assumed value of 10.0000m. Secondary TBM is a manhole in the road. If this is not appropriate, please advise if a deep datum is required?
- Further reads to be taken in Mar 24

File 6686348 Level Reading 16 [91132253].xls.XLS

Readings


Printed on 15/02/2024

FRONT



LEVEL MONITORING - RELATIVE MOVEMENT SKETCH

Client: Sedgwick






Notes:
Vertical distorted scale 1: 5
Point labels give level difference of last reading from original datum in mm.



LEVEL MONITORING - RELATIVE SURVEY READINGS

Client: Sedgwick

Chart Scale 1:1000



Standard Comments for selection in Readings and Sketch Worksheets
User may edit these as appropriate

Standard Comments	
No Comment	
Standard Comment 1	The Occupier expressed concerns
Standard Comment 2	The Occupier expressed no new concerns
Standard Comment 3	Standard Comment 3
Standard Comment 4	Standard Comment 4
Standard Comment 5	

Standard Bullet
•