

APPENDIX 3


G7357- M1 18.03.24



- The points could not be taken on a common brickcourse subsequently relative data only

LEVEL MONITORING - RELATIVE MOVEMENT SKETCH

Client: David Carr Consulting Engineers Ltd



Datum Reading	Reading 1 (15/9/23)	Reading 2 (12/10/23)	Reading 3 (15/11/23)	Reading 4 (13/12/23)	Reading 5 (22/2/24)	Reading 6 (0/1/00)
Reading 7 (0/1/00)	Reading 8 (0/1/00)	Reading 9 (0/1/00)	Reading 10 (0/1/00)	Reading 11 (0/1/00)	Reading 12 (0/1/00)	Reading 13 (0/1/00)
Reading 14 (0/1/00)	Reading 15 (0/1/00)	Reading 16 (0/1/00)	Reading 17 (0/1/00)	Reading 18 (0/1/00)	Reading 19 (0/1/00)	Reading 20 (0/1/00)

Notes:

Vertical distorted scale 1: 150

Point labels give level difference of last reading from original datum in mm.



GRYPHON SURVEYS LTD.
01277 212794
www.gryphon-surveys.co.uk

LEVEL MONITORING - RELATIVE SURVEY READINGS

Client: David Carr Consulting Engin

Chart Scale 1:1000

