

## Site Photographs



Lower ground floor rear – glazed door to be replaced.



Rear elevation of 6 Handel St, upper ground floor and above.



Rear elevation of 6 Handel St, upper ground floor and above.





7 Handel St showing original window opening.



Internal – non-original wardrobe to be demolished.






Existing drain that new WC will drain into.



Interior – wardrobe to be demolished





Interior – wardrobe to be demolished





Existing glazed door to be replaced.