



General Arrangement Notes

Not in scope

Area in scope

1

2

3

Note:  
1. Primary window to be made good internally. Solar film applied to internal face.  
2. Where 's' denotes new timber sill board to match retained timber sill