
1, 4 & 7 Triton Square Isolations

Date: 1st March 2018

1. The two High Voltage (HV) JP Morgan supplies were disconnected and the cables cut from within the UKPN sub-station and in the switch rooms.



JP Morgan HV cables cut from within the UKPN switch room.




JP Morgan HV cables cut from within the two switch rooms.

2. The Landlords HV supplies were racked out and the EPO pushed to isolate power back to the UKPN substation.
















3. The three Low Voltage supplies to the Gym, Nursery and Service (unknown supply) were disconnected and the cables cut from within the UKPN substation and within the retail unit.




The Gym (Homes Place), Nursery (Kids Unlimited) and Service (Unknown) supplies cut within the UKPN sub-station.




Gym (Homes Place) and Nursery (Kids Unlimited) supply cut with in UKPN sub-station.



Service (unknown) supply cut within UKPN sub-station.



LV Supply cut from within the gym (Homes Place).



LV supply cut from within the Nursery (Kids Unlimited)

4. The gas supplies to the Landlords Boilers and Gym were shut off and a gas tightness test was carried out to prove the valves hold.



Landlords gas supply isolated



Gym Gas supply isolated

5. All Generator starting batteries were disconnected.

JP Morgan




















Landlords Generators

