

MPAN: - 1200052254133

STULL

DISCONNECTION CERTIFICATE



Customer name: <u>LEND LEASE</u> <u>IAN WALKER</u>	Customer tel/fax no: <u>07930 4600914</u>
Date of disconnection: <u>1-3-18</u>	Project ref/job no: <u>520078382</u>
UK Power Networks contact name: <u>GARY SOUTHGATE</u>	UK Power Networks contact tel no: <u>07850 320538</u>

With effect from: Time 10.00 Date 1-3-18

On behalf of UK Power Networks, I hereby give notice that the following electricity apparatus:

- LV service cable only  LV service cable and service cut-out  HV service cable
- HV service and associated plant  Service cable feeding customers plant/switchgear

which was previously live and at the above location has now been physically disconnected from UK Power Networks distribution networks. As this certificate only relates to the disconnection at any single point, there is a possibility that if the site is a multi occupancy building or dwelling then other services and/or cables and apparatus may still be present and 'live'. Therefore cable drawings should be requested (see overleaf) and excavation work only proceed in accordance with the Health and Safety Executives guidance document HS(G)47 - "Avoiding Danger from Underground Services", QR in the case of overhead apparatus GS6 "Avoiding Danger from Overhead Lines". If further advice is required please contact us on any of the telephone number(s) shown above or on reverse.

Acknowledgement of customer

I acknowledge receipt of this document and confirm that all staff in my charge including sub-contractors **WILL BE** made aware of the above.

Date sent/left on site Time 10.00 Date 1-3-18

Signed\* [Signature]

Name IAN WALKER

\*On behalf of the customer or customer's representative

For your guidance, your attention is drawn to the general advice on the reverse of this sheet.

(The following is for UK Power Networks purposes and should only be filled in by UK Power Networks staff)

Details of underground / overhead apparatus conductors disconnected

Service head removed YES/NO [Signature]  
(Please state size and type) \_\_\_\_\_ AMP

Three phase  Single phase

LV cable strapped back to the main YES/NO [Signature]  
(If NO please state reason why this was not carried out e.g. site hoarding, scaffolding etc and show on sketch where cable has been pot-ended) \_\_\_\_\_

CABLE CUT BOTH ENDS  
HV SERVICE NO. 2  
FROM EAST SWITCH  
BOARD  
21376 TRITON SQ  
EAST SW PNL

UK Power Networks operative's name GARY Signed [Signature] Date 1-3-18

SOUTHGATE

MPAN: 12000 52254142

**DISCONNECTION CERTIFICATE**



Customer name: <u>LEND LEASE</u> <u>IAN WALKER</u>	Customer tel/fax no: <u>07930 40094</u>
Date of disconnection: <u>1-3-18</u>	Project ref/job no: <u>520078382</u>
UK Power Networks contact name: <u>GARY SOUTHGATE</u>	UK Power Networks contact tel no: <u>07850 320 538</u>

With effect from: Time 10.41 Date 13-1-18

On behalf of UK Power Networks, I hereby give notice that the following electricity apparatus:

- LV service cable only  LV service cable and service cut-out  HV service cable
- HV service and associated plant  Service cable feeding customers plant/switchgear

which was previously live and at the above location has now been physically disconnected from UK Power Networks distribution networks. As this certificate only relates to the disconnection at any single point, there is a possibility that if the site is a multi occupancy building or dwelling then other services and/or cables and apparatus may still be present and 'live'. Therefore cable drawings should be requested (see overleaf) and excavation work only proceed in accordance with the Health and Safety Executives guidance document HS(G)47 - "Avoiding Danger from Underground Services", OR in the case of overhead apparatus GS6 "Avoiding Danger from Overhead Lines". If further advice is required please contact us on any of the telephone number(s) shown above or on reverse.

**Acknowledgement of customer**

I acknowledge receipt of this document and confirm that all staff in my charge including sub-contractors **WILL BE** made aware of the above.

Date sent/left on site Time 10.41 Date 13-1-18

Signed\* [Signature] Name IAN WALKER  
\*On behalf of the customer or customer's representative

**For your guidance, your attention is drawn to the general advice on the reverse of this sheet.**

(The following is for UK Power Networks purposes and should only be filled in by UK Power Networks staff)

**Details of underground/ overhead apparatus conductors disconnected**

Service head removed YES/NO  
(Please state size and type) \_\_\_\_\_ AMP  
 Three phase  Single phase  
LV cable strapped back to the main YES/NO  
(If NO please state reason why this was not carried out e.g. site hoarding, scaffolding etc and show on sketch where cable has been pot-ended)

CABLE CUT BOTH ENDS  
H.V. SERVICE NO. 2  
FROM EAST SWITCH  
BOARD 21376  
TRITON SQ EAST SW  
PAGE

UK Power Networks operative's name GARY Signed [Signature] Date 1-3-18  
SOUTHGATE

MPAN: 12200050850214

DISCONNECTION CERTIFICATE



Customer name: <u>LEND LEASE</u> <u>IAN WALKER</u>	Customer tel/fax no: <u>07930 400914</u>
Date of disconnection: <u>1-3-18</u>	Project ref/job no: <u>520078382</u>
UK Power Networks contact name: <u>GARY SOUTHGATE</u>	UK Power Networks contact tel no: <u>07850 320538</u>

With effect from : Time \_\_\_\_\_ Date \_\_\_\_\_

On behalf of UK Power Networks, I hereby give notice that the following electricity apparatus:

LV service cable only  LV service cable and service cut-out  HV service cable

HV service and associated plant  Service cable feeding customers plant/switchgear

which was previously live and at the above location has now been physically disconnected from UK Power Networks distribution networks. As this certificate only relates to the disconnection at any single point, there is a possibility that if the site is a multi occupancy building or dwelling then other services and/or cables and apparatus may still be present and 'live'. Therefore cable drawings should be requested (see overleaf) and excavation work only proceed in accordance with the Health and Safety Executives guidance document HS(G)47 - "Avoiding Danger from Underground Services", QR in the case of overhead apparatus GS6 "Avoiding Danger from Overhead Lines". If further advice is required please contact us on any of the telephone number(s) shown above or on reverse.

Acknowledgement of customer

I acknowledge receipt of this document and confirm that all staff in my charge including sub-contractors **WILL BE** made aware of the above.

Date sent/left on site Time 12:00 Date 1-3-18

Signed\* [Signature]  
\*On behalf of the customer or customer's representative

Name IAN WALKER

**For your guidance, your attention is drawn to the general advice on the reverse of this sheet.**

(The following is for UK Power Networks purposes and should only be filled in by UK Power Networks staff)

Details of underground / overhead apparatus conductors disconnected

Service head removed YES/NO N/A  
(Please state size and type) \_\_\_\_\_ AMP

Three phase  Single phase

LV cable strapped back to the main YES/NO  
(If NO please state reason why this was not carried out e.g. site hoarding, scaffolding etc and show on sketch where cable has been pot-ended) NO

CABLE CUT AFTER FUSES  
REMOVE ABOVE LV BOARD  
AS CABLE LEFT SUBSTATION  
AND CUSTOMERS END

SUBSTATION SERVICE

UK Power Networks operative's name GARY Signed [Signature] Date 1-3-18

SOUTHGATE

M PAW : 1200010028789

DISCONNECTION CERTIFICATE



Customer name: <u>LEMP LEASE</u> <u>IAN WALKER</u>	Customer tel/fax no: <u>079301100911</u>
Date of disconnection: <u>1-3-18</u>	Project ref/job no: <u>920078382</u>
UK Power Networks contact name: <u>GARY SOUTHGATE</u>	UK Power Networks contact tel no: <u>07850 320 538</u>

With effect from : Time 12.00 Date 1-3-18

On behalf of UK Power Networks, I hereby give notice that the following electricity apparatus:

- LV service cable only  LV service cable and service cut-out  HV service cable
- HV service and associated plant  Service cable feeding customers plant/switchgear

which was previously live and at the above location has now been physically disconnected from UK Power Networks distribution networks. As this certificate only relates to the disconnection at any single point, there is a possibility that if the site is a multi occupancy building or dwelling then other services and/or cables and apparatus may still be present and 'live'. Therefore cable drawings should be requested (see overleaf) and excavation work only proceed in accordance with the Health and Safety Executives guidance document HS(G)47 - "Avoiding Danger from Underground Services", OR in the case of overhead apparatus GS6 "Avoiding Danger from Overhead Lines". If further advice is required please contact us on any of the telephone number(s) shown above or on reverse.

Acknowledgement of customer

I acknowledge receipt of this document and confirm that all staff in my charge including sub-contractors **WILL BE** made aware of the above.

Date sent/left on site Time 12.00 Date 1-3-18

Signed\* [Signature]  
\*On behalf of the customer or customer's representative

Name IAN WALKER

**For your guidance, your attention is drawn to the general advice on the reverse of this sheet.**

(The following is for UK Power Networks purposes and should only be filled in by UK Power Networks staff)

Details of underground / overhead apparatus conductors disconnected

Service head removed YES/NO NA  
 (Please state size and type) \_\_\_\_\_ AMP  
 Three phase  Single phase  
 LV cable strapped back to the main YES/NO  
 (If NO please state reason why this was not carried out e.g. site hoarding, scaffolding etc and show on sketch where cable has been pot-ended) NO

CABLE CUT AFTER FUSES  
 REMOVED ON LV BOARD.  
 CUT ABOVE BOARD,  
 AS LEFT SUBSTATION  
 AND AT CUSTOMER'S  
 END

SUBSTATION SERVICE

UK Power Networks operative's name GARY SOUTHGATE Signed [Signature] Date 1-3-18

NO MPAN SERVICE ALREADY  
DEAD

DISCONNECTION CERTIFICATE



Customer name: <u>LEAD LEAD</u> <u>IAN WALKER</u>	Customer tel/fax no: <u>07930 400914</u>
Date of disconnection: <u>1-3-18</u>	Project ref/job no: <u>520028382</u>
UK Power Networks contact name: <u>GARY SOUTHGATE</u>	UK Power Networks contact tel no: <u>07850 370538</u>

With effect from: Time 12:00 Date 1-3-18

On behalf of UK Power Networks, I hereby give notice that the following electricity apparatus:

- LV service cable only  LV service cable and service cut-out  HV service cable
- HV service and associated plant  Service cable feeding customers plant/switchgear

which was previously live and at the above location has now been physically disconnected from UK Power Networks distribution networks. As this certificate only relates to the disconnection at any single point, there is a possibility that if the site is a multi occupancy building or dwelling then other services and/or cables and apparatus may still be present and 'live'. Therefore cable drawings should be requested (see overleaf) and excavation work only proceed in accordance with the Health and Safety Executives guidance document HS(G)47 - "Avoiding Danger from Underground Services", OR in the case of overhead apparatus GS6 "Avoiding Danger from Overhead Lines". If further advice is required please contact us on any of the telephone number(s) shown above or on reverse.

**Acknowledgement of customer**

I acknowledge receipt of this document and confirm that all staff in my charge including sub-contractors **WILL BE** made aware of the above.

Date sent/left on site Time 12:00 Date 1-3-18

Signed\* [Signature]  
\*On behalf of the customer or customer's representative

Name IAN WALKER

**For your guidance, your attention is drawn to the general advice on the reverse of this sheet.**

(The following is for UK Power Networks purposes and should only be filled in by UK Power Networks staff)

**Details of underground / overhead apparatus conductors disconnected**

Service head removed YES/NO  
(Please state size and type) \_\_\_\_\_ AMP  
 Three phase  Single phase  
 LV cable strapped back to the main YES/NO  
 (If NO please state reason why this was not carried out e.g. site boarding, scaffolding etc and show on sketch where cable has been pot-ended)  
 \_\_\_\_\_  
 \_\_\_\_\_

SERVICE CABLE ON  
 SERVICE ALREADY  
 WITH FUSES REMOVED  
 CABLE CUT ABOVE  
 LV BOARD AND  
 AT LEADING SOUTHCOTE

UK Power Networks operative's name GARY Signed [Signature] Date 1-3-18  
SOUTHCOTE