

Union Chapel, Compton Avenue, London N1 2XD www.rmears.co.uk

tel: 020 7359 8222 email: rma@rmears.co.uk

Refurbishment and repair works at 45 Great Ormond Street, London WC1N 3HZ

Photos



Front elevation



Shopfront and entrance door at front



Front elevation – Entrance door




Rear elevation



Rear lightwell and extension

## INTERIORS – GROUND FLOOR




Hallway and staircase



Half landing

INTERIOR – FIRST FLOOR



Frist floor landing and staircase





Front room





Front room





Rear Room





Rear room



Door to bathroom and bathroom



Half landing and staircase to second floor

INTERIOR – SECOND FLOOR



Second floor landing/lobby and staircase to third floor





Front room





Front room











Bathroom



Door to the bathroom and bathroom



Half landing and staircase to third floor

INTERIOR – THIRD FLOOR



## Third floor landing



Front room



Large front room



Large front room



Large front room



Small front room



Small front room



Small front room



Rear room



Rear room





Rear Room