

<b>Application No:</b>	<b>Consultees Name:</b>	<b>Received:</b>	<b>Comment:</b>	<b>Response:</b>
2023/4030/P	CRASH	24/06/2024 14:43:30	COMMNT	The elevational drawing appears to show window CA4 as having some form of louvre in the top left light but clear glass in the window detail drawing. Which is correct?

---