

29 Edis Street, London, NW1 8LE

MONITORING

CRACK MONITORING

for SMS (LV)

29 Edis Street, London, NW1 8LE

Client: SMS (LV)
Client Contact: Robbie Taylor
Claim Number: [REDACTED]
Client Reference: [REDACTED]
Policy Holder: [REDACTED]
Report Date: 17 July 2024
Our Ref: [REDACTED]

SubsNetuk


Crack Monitoring Readings

The following table shows the reading levels of the Crack Monitoring Stations.

Date	A=B (H)	B=C (D)	A=C (V)(C)	Crack Width
C1 - Landing (Front ground floor) ceiling near WC				
15 February 2023	66.12	89.06	65.51	1.30 - 2.00
28 April 2023	65.91	88.91	65.45	1.60 - 1.70
12 July 2023	66.33	89.27	65.46	2.30 - 2.30
8 September 2023	67.30	89.97	65.45	4.40
19 January 2024	66.31	89.40	65.51	3.80 - 1.90
8 April 2024	65.85	89.06	65.53	4.50 - 1.80
17 July 2024	65.73	89.03	65.47	

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



29 Edis Street, London, NW1 8LE

MONITORING

Site Visit Notes

SubsNetuk