



Appendix J – First floor

No.18




Front room [left] and rear room [left]: Unauthorised door architraves (**ARC**), skirting boards (**SKT**), modern doors (**D**), kitchenettes (**KIT**), recessed LED track lightings (**LED**), & full height ensuite partitions (highlighted **blue**).

No.20



Front room: Unauthorised door architraves (**ARC**), skirting boards (**SKT**), modern doors (**D**), kitchenettes (**KIT**), recessed LED track lightings (**LED**), & full height ensuite partitions (highlighted **blue**).



Rear room: Unauthorised door architraves (**ARC**), skirting boards (**SKT**), modern doors (**D**), kitchenettes (**KIT**), recessed LED track lightings (**LED**), damage to chimney breast (circled **orange**) – further depicted in Appendix 13 – & full height ensuite partitions (highlighted **blue**).