



Appendix R – Ground and rear rooms: Ensuite ground to ceiling infills.

No.18




Ground floor front room [left] and rear room [right]: Unauthorised ensuite designs.




First floor front room [left] and rear room [right]: Unauthorised ensuite designs.

No.20




Ground floor front room [left] and rear room [right]: Unauthorised ensuite designs.



First floor front room [left] and rear room [right]: Unauthorised ensuite designs.

Appendix S – Drawing “2245-19” of the 2023/0285/L consent – Nos.18-20.




Appendix T – No.18 ground floor rear room and No.20 ground floor hallway: Party wall breach



Unauthorised party wall breach, unauthorised door architraves (**ARC**) and modern door (**D**) too.

Appendix U – Basement front rooms.

[Right]: No.18. [Left] No.20.



Access to the lightwell storage room boarded up (circled red – internal // circled orange – external)