



**76948/K**

**Certificate No.**  
**3**

**Date of Test**  
**23/4/24**

**BRICK TEST RESULTS**  
**WATER ABSORPTION (by cold water absorption)**  
BS EN 772-21: 2011

Project	(AE1613) 71 AR 240301
Sandberg Sample Reference	K19074
Client Sample Reference	71 Avenue Road
Number of test Specimens	6
Type of Brick	Reclaimed
Soaking Period, hours	24 hrs, 10 mins

Sandberg Specimen Reference	Client Specimen Reference	Specimen Mass		Water Absorption <sup>1</sup> , %
		Oven Dried g	Saturated, g	
K19074/1	71 Ave Rd Sample 1-907 Acacia Rd, GF, Lift+Lift Lobby	2093.6	2410.4	15
K19074/3	71 Ave Rd Sample 3-907 Acacia Rd, GF, Entrance Hall	2167.7	2519.9	16
K19074/6	71 Ave Rd Sample 6-907 Acacia Rd, FF+Her Ensuite	2033.0	2360.3	16
K19074/7	71 Ave Rd Sample 7-907 Acacia Rd, FF+Guest Bedroom 2	2222.2	2378.4	7
K19074/9	71 Ave Rd Sample 9-907 Acacia Rd, FF+ Seasonal Dressing Room	2204.5	2532.1	15
K19074/14	71 Ave Rd Sample 14-907 Acacia Rd, Fitness Studio, 2 <sup>nd</sup> Fl	2301.3	2686.5	17
			Average <sup>1</sup>	14
Remarks:				

<sup>1</sup> to nearest 1%

<b>Client</b>	SHH Architecture & Interior Design 1 Vencourt Place London W6 9NU	<b>Signed</b>	For Sandberg LLP 
	For the attention of	<b>Name</b>	John Gallagher
		<b>Position</b>	Deputy Quality Manager
<b>Reference</b>		<b>Date</b>	26 April 2024

The results contained in this certificate apply to the sample as received and tested. This certificate shall not be reproduced except in full without the written approval of Sandberg LLP. Materials, samples and test specimens are retained for a period of 2 months from the issue of the this test certificate. Opinions and interpretations expressed herein are outside the scope of UKAS accreditation.

**End of Report**