


EXISTING DRAWINGS PREPARED + PROVIDED BY OTHERS, SHOWN HERE INDICATIVELY. NEIGHBOURING PROPERTIES SHOWN FOR ILLUSTRATION ONLY.

CONTRACTOR TO BE AWARE OF POTENTIAL HAZARDOUS MATERIALS, NOTABLY THE PRESENCE OF ASBESTOS.



APARTMENT FLOOR PLAN



FRONT ELEVATION



EXISTING PLANS + ELEVATIONS

SITE ADDRESS: 11 BUCKLAND CRESCENT, BELSIZE PARK, LONDON, NW3 5DH

A: 25.10.24 PLANNING ISSUE DRAWINGS
B: 29.10.24: VISUAL ALTERATIONS TO LPA COMMENTS
C: 30.10.24: ADD NOTES + DETAILS TO LPA COMMENTS

2418/01-IC

CLIENT: JONES
DATE: OCT 2024
SCALE: 1:100 @ A3

11 BUCKLAND CRESCENT
BELSIZE PARK
LONDON, NW3 5DH

Nieves
DESIGN | SPACE
T: 07903 160 851 | E: DESIGNSPACE@OUTLOOK.COM

EXISTING DRAWINGS PREPARED + PROVIDED BY OTHERS, SHOWN HERE INDICATIVELY. NEIGHBOURING PROPERTIES SHOWN FOR ILLUSTRATION ONLY.

CONTRACTOR TO BE AWARE OF POTENTIAL HAZARDOUS MATERIALS, NOTABLY THE PRESENCE OF ASBESTOS.



Side windows with security grilles shown indicatively.
Neighbouring conservatory serving roof terrace shown in background.

SIDE ELEVATION



REAR ELEVATION



EXISTING ELEVATIONS

SITE ADDRESS: 11 BUCKLAND CRESCENT, BELSIZE PARK, LONDON, NW3 5DH

A: 25.10.24 PLANNING ISSUE DRAWINGS
B: 29.10.24: VISUAL ALTERATIONS TO LPA COMMENTS
C: 30.10.24: ADD NOTES + DETAILS TO LPA COMMENTS

2418/01-2C


CLIENT: JONES
DATE: OCT 2024
SCALE: 1:100 @ A3

11 BUCKLAND CRESCENT
BELSIZE PARK
LONDON, NW3 5DH

Nieves
DESIGN | SPACE
T: 07903 160 851 E: DESIGNSPACE@OUTLOOK.COM

EXISTING DRAWINGS PREPARED + PROVIDED BY OTHERS, SHOWN HERE INDICATIVELY. NEIGHBOURING PROPERTIES SHOWN FOR ILLUSTRATION ONLY.

CONTRACTOR TO BE AWARE OF POTENTIAL HAZARDOUS MATERIALS, NOTABLY THE PRESENCE OF ASBESTOS.



APARTMENT FLOOR PLAN



FRONT ELEVATION

Window with metal security railing set within reveal. Security railings to be retained. Timber window behind to be replaced with new double glazed timber unit, painted white, to match the existing style and appearance.
 External window opening dressing retained / reinstated to match.
 Existing doors / windows to apartment to be replaced with new double glazed timber units, painted white, to match the existing style and appearance.

Window with metal security railing set within reveal. Security railings to be retained. Timber window behind to be replaced with new double glazed timber unit, painted white, to match the existing style and appearance.
 Window behind security railing



PROPOSED PLANS + ELEVATIONS

SITE ADDRESS: 11 BUCKLAND CRESCENT, BELSIZE PARK, LONDON, NW3 5DH

A: 29.10.24: VISUAL ALTERATIONS TO LPA COMMENTS
 B: 30.10.24: ADD NOTES + DETAILS TO LPA COMMENTS

2418/03-1B

CLIENT: JONES
 DATE: OCT 2024
 SCALE: 1:100 @ A3

11 BUCKLAND CRESCENT
 BELSIZE PARK
 LONDON, NW3 5DH


Nieves DESIGN | SPACE
 T: 07903 160 851 | E: DESIGNSPACE@OUTLOOK.COM

EXISTING DRAWINGS PREPARED + PROVIDED BY OTHERS, SHOWN HERE INDICATIVELY. NEIGHBOURING PROPERTIES SHOWN FOR ILLUSTRATION ONLY.

CONTRACTOR TO BE AWARE OF POTENTIAL HAZARDOUS MATERIALS, NOTABLY THE PRESENCE OF ASBESTOS.



SIDE ELEVATION



REAR ELEVATION



PROPOSED ELEVATIONS

SITE ADDRESS: 11 BUCKLAND CRESCENT, BELSIZE PARK, LONDON, NW3 5DH

A: 29.10.24: VISUAL ALTERATIONS TO LPA COMMENTS
B: 30.10.24: ADD NOTES + DETAILS TO LPA COMMENTS

2418/03-2B

CLIENT: JONES
DATE: OCT 2024
SCALE: 1:100 @ A3

11 BUCKLAND CRESCENT
BELSIZE PARK
LONDON, NW3 5DH

Nieves
DESIGN | SPACE
T: 07903 160 851 E: DESIGNSPACE@OUTLOOK.COM