

Monitoring Details:

Level Monitoring

Provider Name: My Home Needs

Monitoring Interval: Every 8 weeks

Instruction Date: 06/07/2022

Number of Visits: 7

Reading Date: 18/09/2024

Visits Completed: 7

Date of Issue: 20/09/2024

Visits Outstanding: 0

Client Details:

Client: Crawfords

Engineer / Handler: -

Job Reference:


Monitored Address:

Address: 22a Harley Road, Hampstead, London, NW3 3BN

Front Elevation



Site Plan



Visit Notes

No visit notes have been entered for any visits


Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	12/09/23	20/11/23	02/02/24	28/03/24	29/05/24	26/07/24	18/09/24	
TBM1	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	
2	9.5417	9.5430	9.5428	9.5444	9.5443	9.5415	9.5394	
3	9.5331	9.5348	9.5424	9.5430	9.5428	9.5365	9.5291	
4	9.5449	9.5460	9.5517	9.5523	9.5518	9.5464	9.5424	
5	9.5697	9.5705	9.5712	9.5708	9.5701	9.5693	9.5708	
6	9.7045	9.7037	9.7032	9.7037	9.7034	9.7030	9.7066	
Taken by	N/A	N/A	BA	RS	BJ	BJ	RN	
Serial number			522955	1212368	523158	523158	118	


Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	12/09/23	20/11/23	02/02/24	28/03/24	29/05/24	26/07/24	18/09/24	
TBM1	0	0	0	0	0	0	0	
2	0	+13	+11	+2.7	+2.6	-0.2	-2.3	
3	0	+1.7	+9.3	+9.9	+9.7	+34	-4	
4	0	+11	+6.8	+74	+6.9	+15	-2.5	
5	0	+0.8	+15	+11	+0.4	-0.4	+11	
6	0	-0.8	-13	-0.8	-11	-15	+21	

Level Readings Chart (Points TBM 1 - 6)



Relative Movement (Relative Survey, for illustration purposes only)



11/09/2023

20/11/2023

02/02/2024

28/03/2024

28/05/2024

25/07/2024

17/09/2024