

Basement Impact Assessment Audit

27 Elizabeth Mews, London NW3 4UH

> For London Borough of Camden

> > Project No. 14006-96

Date October 2024

Campbell Reith Hill LLP 15 Bermondsey Square London SE1 3UN

T: +44 (0)20 7340 1700 E: london@campbellreith.com W: www.campbellreith.com



DOCUMENT HISTORY AND STATUS

| Revision | Date | Purpose/ Status | File Ref | Author | Check | Review |
|----------|------------|--------------------|---|--------|-------|--------|
| D1 | 02/10/2024 | For comment | SSra-14006-96-021024 - 27 Elizabeth Mews_D1 | SS | RA | EMB |

This document has been prepared in accordance with the scope of Campbell Reith Hill LLP's (CampbellReith) appointment with its client and is subject to the terms of the appointment. It is addressed to and for the sole use and reliance of CampbellReith's client. CampbellReith accepts no liability for any use of this document other than by its client and only for the purposes, stated in the document, for which it was prepared and provided. No person other than the client may copy (in whole or in part) use or rely on the contents of this document, without the prior written permission of Campbell Reith Hill LLP. Any advice, opinions, or recommendations within this document should be read and relied upon only in the context of the document as a whole. The contents of this document are not to be construed as providing legal, business or tax advice or opinion.

© Campbell Reith Hill LLP 2024

Document Details

| Last Saved | 02/10/2024 09:09 | |
|--------------------|--|--|
| Author | S Savery, BSc MSc CGeol FGS | |
| Project Partner | E M Brown, BSc MSc CGeol FGS | |
| Project Number | 14006-96 | |
| Project Name | Basement Impact Assessment Audit | |
| Revision | D1 | |
| Planning Reference | 2024/2988/P | |
| File Ref | SSra-14006-96-021024 - 27 Elizabeth Mews_D1.docx | |



CONTENTS

| 1.0 | NON-TECHNICAL SUMMARY | 4 |
|-----|---|----|
| 2.0 | INTRODUCTION | 5 |
| 3.0 | BASEMENT IMPACT ASSESSMENT AUDIT CHECK LIST | 7 |
| 4.0 | DISCUSSION | 10 |
| 5.0 | CONCLUSIONS | 14 |

APPENDICES

Appendix 1 Consultation Responses Appendix 2 Audit Query Tracker Appendix 3 Supplementary Supporting Documents



1.0 NON-TECHNICAL SUMMARY

- 1.1 CampbellReith was instructed by London Borough of Camden, (LBC) to carry out an audit on the Basement Impact Assessment submitted as part of the Planning Submission documentation for 27 Elizabeth Mews London NW3 4UH (planning reference 2024/2988/P). The basement is considered to fall within Category B as defined by the Terms of Reference.
- 1.2 The Audit reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development in accordance with LBC's policies and technical procedures.
- 1.3 CampbellReith was able to access LBC's Planning Portal and gain access to the latest revision of submitted documentation and reviewed it against an agreed audit check list.
- 1.4 The BIA has been prepared using individuals who possess suitable qualifications.
- 1.5 The BIA has confirmed that the proposed basement will be founded 3.50m below ground level.
- 1.6 It is unlikely that groundwater will be encountered during basement foundation excavation. BIA recommendations include mitigation measures to control localised water ingress.
- 1.7 It is accepted that the development will not impact on the wider hydrogeology of the area.
- **1.8** It is accepted that the basement will not impact the hydrology of the area and the site is not in an area subject to flooding.
- 1.9 Utility plans should be provided.
- **1.10** The structural calculations provided should be updated using the geotechnical parameters provided in the BIA.
- **1.11** The BIA outlines the construction sequence however, the number of underpin stages/ lifts should be clearly stated and the assessments revised accordingly.
- **1.12** The BIA predicts potential damage to neighbouring structures can be controlled within acceptable limits although this should be remeasured with the revised submission.
- 1.13 Confirmation of the anticipated impact to the highways and buried services is requested.
- 1.14 As described in Section 5, it cannot be confirmed that the BIA complies with the requirements of CPG: Basements and the Principles for Audit set out in the Basement Impact Assessment (BIA) Audit Service Terms of Reference & Audit Process. Queries and comments on the BIA are described in Section 4 and Appendix 2.



2.0 INTRODUCTION

- 2.1 CampbellReith was instructed by London Borough of Camden (LBC) on 18th August 2024 to carry out a Category B audit on the Basement Impact Assessment (BIA) submitted as part of the Planning Submission documentation for 27 Elizabeth Mews, London NW3 4UH, and Planning Reference 2024/2988/P.
- 2.2 The audit was carried out in accordance with the Terms of Reference set by LBC. It reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development.
- 2.3 A BIA is required for all planning applications with basements in Camden in general accordance with policies and technical procedures contained within
 - Camden Local Plan 2017 Policy A5 Basements.
 - Camden Planning Guidance (CPG): Basements. January 2021.
 - Guidance for Subterranean Development (GSD). Issue 01. November 2010. Ove Arup & Partners.
- 2.4 The BIA should demonstrate that schemes:
 - a) maintain the structural stability of the building and neighbouring properties;
 - b) avoid adversely affecting drainage and run off or causing other damage to the water environment;
 - c) avoid cumulative impacts upon structural stability or the water environment in the local area;

and evaluate the impacts of the proposed basement considering the issues of hydrology, hydrogeology and land stability via the process described by the GSD and to make recommendations for the detailed design.

- 2.5 LBC's Audit Instruction described the planning proposal as "*Excavation for a new basement extension, erection of a new dormer roof extension including external alterations for new office space at basement and ground floor levels and the change of use of the first floor from office accommodation to 1 x self-contained flat at first and second floor level.*"
- 2.6 The Audit Instruction confirmed 27 Elizabeth Mews, London NW3 4UH is not involved, or neighbour to, listed buildings.
- 2.7 CampbellReith accessed LBC's Planning Portal on 17th September 2024 and gained access to the following relevant documents for audit purposes:
 - Basement Impact Assessment Report (BIA) by Geotechnical & Environmental Associates Limited (GEA), ref. J23095, rev. 1, dated 11th July 2024.
 - BIA Structural Design by Harrison Shortt Structural Engineers Ltd. ref. 2421_Issue 01, rev. B, dated 3rd May 2024.



- Construction Management Plan Proforma completed by Rohan Sherlock of Sherlock London Ltd. ref. -, rev. 01, dated 8th April 2024.
- Flood Risk Assessment (FRA) by Evans River and Coastal Ltd. ref. 3202/RE/05-23/01, rev. 01, dated May 2024.
- Site Location Plan by Charlton Brown Architecture & Interiors, ref. 21026 PR-100, rev.
 -, dated 22nd June 2022.
- Existing Plans Elevations and Sections by Charlton Brown Architecture & Interiors, ref. 21026, rev. -, dated 22nd June 2022:
 - Floor Plans, ref. PR-101
 - Sections AA, ref. PR-102
 - Elevation NW, ref. PR-103
 - Elevation NE, ref. PR-104
- Proposed Plans Elevations and Sections by Charlton Brown Architecture & Interiors, ref. 21026, rev. -, dated 22nd June 2022:
 - Floor Plans, ref. PR-105 and PR-106
 - Sections AA, ref. PR-107
 - Elevation NW, ref. PR-108
 - Elevation NE, ref. PR-109
- Demolition Plans Elevations and Sections by Charlton Brown Architecture & Interiors, ref. 21026, rev. -, dated 22nd June 2022:
 - Floor Plans, ref. PR-110
 - Sections AA, ref. PR-111
 - Elevation NW, ref. PR-112
 - Elevation NE, ref. PR-113
- Consultation Responses



3.0 BASEMENT IMPACT ASSESSMENT AUDIT CHECK LIST

| Item | Yes/No/NA | Comment |
|--|-----------|-------------------------------------|
| Are BIA Author(s) credentials satisfactory? | Yes | BIA section 1.3.2 |
| Is data required by Cl.233 of the GSD presented? | Yes | |
| Does the description of the proposed development include all aspects of temporary and permanent works which might impact upon geology, hydrogeology and hydrology? | Yes | |
| Are suitable plan/maps included? | No | Utility plans should be provided |
| Do the plans/maps show the whole of the relevant area of study and do they show it in sufficient detail? | Yes | |
| Land Stability Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers? | Yes | BIA section 3.2 |
| Hydrogeology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers? | Yes | BIA section 3.1 |
| Hydrology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers? | Yes | BIA section 3.3 |
| Is a conceptual model presented? | Yes | BIA section 7.0 |
| Land Stability Scoping Provided? Is scoping consistent with screening outcome? | Yes | BIA section 4.0 |
| Hydrogeology Scoping Provided? Is scoping consistent with screening outcome? | NA | No items brought through to scoping |

Basement Impact Assessment Audit 27 Elizabeth Mews, London NW3 4UH



| Item | Yes/No/NA | Comment |
|--|-----------|-------------------------------------|
| Hydrology Scoping Provided? Is scoping consistent with screening outcome? | NA | No items brought through to scoping |
| Is factual ground investigation data provided? | Yes | BIA appendix A |
| Is monitoring data presented? | No | |
| Is the ground investigation informed by a desk study? | Yes | BIA section 2.0 |
| Has a site walkover been undertaken? | Yes | |
| Is the presence/absence of adjacent or nearby basements confirmed? | Yes | BIA section 9.1 |
| Is a geotechnical interpretation presented? | Yes | |
| Does the geotechnical interpretation include information on retaining wall design? | Yes | BIA section 8.1.1 |
| Are reports on other investigations required by screening and scoping presented? | Yes | Flood Risk Assessment provided. |
| Are the baseline conditions described, based on the GSD? | Yes | BIA section 5.0 |
| Do the baseline conditions consider adjacent or nearby basements? | Yes | BIA section 9.1 |
| Is an Impact Assessment provided? | Yes | BIA Part 4 |
| Are estimates of ground movement and structural impact presented? | Yes | BIA section 10.0 |

Basement Impact Assessment Audit 27 Elizabeth Mews, London NW3 4UH



| Item | Yes/No/NA | Comment |
|--|-----------|--|
| Is the Impact Assessment appropriate to the matters identified by screening and scoping? | No | The GMA should include consideration of the impact to the highway. |
| Has the need for mitigation been considered and are appropriate mitigation methods incorporated in the scheme? | Yes | |
| Has the need for monitoring during construction been considered? | Yes | BIA section 11.2 |
| Have the residual (after mitigation) impacts been clearly identified? | No | Consideration of the impact to highways has not been included in the GMA. |
| Has the scheme demonstrated that the structural stability of the building and neighbouring properties and infrastructure will be maintained? | Yes | BIA section 11.0 however, some further clarification is required as outlined in Section 4.0 below. |
| Has the scheme avoided adversely affecting drainage and run- off or causing other damage to the water environment? | Yes | |
| Has the scheme avoided cumulative impacts upon structural stability or the water environment in the local area? | Yes | BIA section 11.0 however, some further clarification is required as outlined in Section 4.0 below. |
| Does report state that damage to surrounding buildings will be no worse than Burland Category 1? | Yes | BIA section 11.0 however, some further clarification is required as outlined in Section 4.0 below. |
| Are non-technical summaries provided? | Yes | BIA Executive Summary |

4.0 **DISCUSSION**

- 4.1 The Basement Impact Assessment (BIA) has been carried out by engineering consultants Geotechnical & Environmental Associates (GEA) and the individuals concerned in its production have suitable qualifications. The BIA Structural Design Report (SDR) has been carried out by Harrison Shortt Structural Engineers Ltd.
- 4.2 The LBC Instruction to proceed with the audit states the basement proposal is neither involved with, nor adjacent to, listed buildings.
- 4.3 The site is within the Belsize Conservation area.
- 4.4 The existing 27 Elizabeth Mews structure comprises a two-storey structure with a flat roof. Proposals involve construction of a new residential floor and mansard extension on the existing structure. The proposed basement will comprise a single-storey beneath the full footprint of the building, with a formation of c.3.50m below the existing ground level at the front of the house.
- 4.5 The BIA has been informed by a desk study and site-specific ground investigation comprising a single borehole to 9.45m below ground level (bgl) of the existing structure. The investigation identified that the ground slab is underlain by Made Ground to a depth of 1.20m over Head Deposits of soft to firm clays to 5.00m bgl. The London Clay Formation, comprising firm to stiff clays, was encountered from 5.00m to the maximum depth of investigation (9.45m bgl).
- 4.6 Groundwater was encountered at 4.50m in BH01. No groundwater monitoring has been undertaken. The BIA recommends that the basement retaining walls are designed to assume groundwater is 1.00m bgl.
- 4.7 Geotechnical parameters have been provided within Section 8.0 of the BIA and are accepted to be suitable for the ground conditions described.
- 4.8 The BIA includes a summary of anticipated foundation depths of the neighbouring property. This is based on publicly available information from nearby planning applications. The findings suggest basements exist beneath the properties fronting onto England's Lane to a depth of 2.50m bgl.
- 4.9 The Subterranean (groundwater) Screening Assessment indicates that the site is underlain by the London Clay Formation, with an aquifer classification as unproductive strata. There are no watercourses or potential spring lines recorded within 100m distance of site.
- 4.10 The screening responses confirm that the development will not alter the area of hardstanding.
- 4.11 The site investigation suggests the basement will not extend below the groundwater table although isolated pockets of perched water maybe encountered. The BIA advises sump pumping is used as a control measure for limited water ingress and that the contractor should have a contingency plan to deal with more significant inflows as a precautionary measure.
- 4.12 It is accepted the will be no significant impact to the local and wider hydrogeological environment.

- 4.13 The Surface Flow and Flooding Screening Assessment states that the site has a very low flooding risk from surface water, sewers, reservoirs (and other artificial sources), groundwater and fluvial/tidal watercourses. The BIA also confirms the nearest lost river is some 450m west of the site.
- 4.14 The Flood Risk Assessment (FRA) confirms the site is within Flood Zone 1 and states the following:
 - there is a low risk of groundwater flooding;
 - there is very low surface water flood risk; and,
 - the site is within an area at low risk of sewer flooding.
- 4.15 It is accepted there will be no impact to the hydrological setting of the area, although this should be confirmed by the LLFA.
- 4.16 The Land Stability Screening Assessment identifies that London Clay is the shallowest stratum and thus there is a potential risk of seasonal shrink swell subsidence. The screening also confirms the site is within 5m of a highway and will significantly increase the differential depth of the foundations relative to neighbouring properties. These items have been brought through the scoping.
- 4.17 Geotechnical laboratory testing has been undertaken to confirm the volume change potential of the near surface soils. The BIA refers to NHBC guidelines and states the basement foundation depths are at sufficient depth that they will not be impacted from seasonal shrink swell subsidence. In addition, the BIA confirms there are no trees in proximity to the proposed basement.
- 4.18 The development is bounded to the northwest and northeast by Elizabeth Mews and Primrose Gardens respectively. Utility plans should be provided as per the scope of engineering services. Underground infrastructure and utilities within the proposed basement's zone of influence should be identified and any impacts upon them assessed, if applicable.
- 4.19 The land stability screening responses identify that the proposed works could potentially impact the surrounding structures and thus a Ground Movement Assessment (GMA) has been undertaken to assess the impact of the proposed basement on the neighbouring structures.
- 4.20 The basement construction method, outlined in the SDR, involves underpinning the existing foundations. The report provided indicates that the underpinning may be carried out in either a single or double lift (depending on the stability of the ground) using a hit-and-miss installation sequence with a maximum excavation width of 1m.
- 4.21 The construction sequence provided in the SDR includes the propping arrangements during construction which will comprise a combination of needle props, perimeter upper-level props and, the basement slab.
- 4.22 Geotechnical parameters are provided within Section 8.0 of the BIA however, the geotechnical parameters used in the structural calculations within the SDR differ from those provided within the BIA. Soil parameters should be presented and used consistently in all assessments/reports.

- 4.23 The BIA indicates a net allowable bearing pressure of 100kN/m² within the firm clays of the Head Deposits and recommends a suspended basement floor slab to accommodate heave.
- 4.24 The GMA is provided within Part 3 of the BIA report. The assessment assumes the basement is to be formed by traditional hit and miss underpinning with a maximum excavation depth of 3.50m. The soil parameters used are accepted to be suitable for the anticipated ground conditions.
- 4.25 The GMA uses Oasys PDisp and XDisp software to predict vertical (heave and settlement) and horizontal/lateral ground movements in two stages of construction:
 - Installation of proposed underpinning.
 - Combined movements from installation and subsequent excavation in front of underpinned walls.
- 4.26 Section 10 of the GMA includes a statement suggesting that the use of CIRIA C760 is considered a conservative approach for underpinning however, CIRIA C760 is intended for the installation of embedded retaining walls, which are not comparable to the method of constructing underpins.
- 4.27 Section 10 also suggests that CampbellReith have set requirements for the minimum horizontal and vertical movement. The values of 5mm to 10mm movement are based on industry experience of underpinning and are therefore considered to meet the requirement of being a cautious and moderately conservative engineering estimate as set out in the Terms of Reference. Reference to CampbellReith should therefore be removed, as this is not factually correct.
- 4.28 A modified movement curve (for a planar diaphragm wall installed in stiff clay from CIRIA C760) has been used to estimate the movements from the underpinning installation. Movements from the basement excavation have been estimated using the CIRIA C760 curve for 'excavations in front of high stiffness wall in stiff clay'. Combined movements indicate total vertical settlements between 5mm to 6mm and horizontal movements of 4mm to 5mm. These correspond with typical movements expected for a single lift of underpinning however, due to the SDR indicating that a double lift of underpinning may be required, an assessment of a two lift underpin construction method should also be provided.
- 4.29 The GMA results indicate short term and long term movements beneath the basement slab (from loading and heave) of -5mm to -8mm respectively, with movements of 2mm to 3mm and 3mm to 5mm beneath the retaining walls.
- 4.30 The neighbouring structures assessed in the GMA include 26, 25 and 25A Elizabeth Mews along with 28A, 28, 30 and 32 England's Lane. The foundation depths of the neighbouring properties have been assumed to be 0.50m bgl however, existing basements along England's Lane are assumed to extend to 2.50m bgl. The building damage assessment results predict damage to the structures will not exceed Burland Damage Category 1 (Very Slight). The damage category should be revised once the above comments have been considered in the GMA.

- 4.31 The potential impact to the public highway and any buried services surrounding the property have not been considered in the GMA and should be assessed.
- 4.32 The BIA states the ground movement predictions should be checked by monitoring the existing structures to ensure no excessive movements occur that would lead to damage.

5.0 CONCLUSIONS

- 5.1 The BIA has been carried out using individuals who possess suitable qualifications as required by CPG Basements.
- 5.2 The BIA has confirmed that the proposed basement will be founded 3.50m below ground level (bgl) within Head Deposits.
- 5.3 The ground investigation findings suggest that groundwater will not be encountered during the basement foundation excavation. The BIA states any perched water encountered can be controlled using sump pumps.
- 5.4 It is accepted that the development will not impact on the local or wider hydrogeology of the area and is not in an area subject to flooding.
- 5.5 Utility information should be provided as per the scope of engineering services.
- 5.6 The BIA suggests the existing basements are present beneath the properties along England's Lane to depths of 2.50m bgl.
- 5.7 The BIA confirms basement construction involves underpinning using a hit and miss method however, the number of lifts/ stages should be confirmed and, the GMA revised accordingly. A construction sequence of the underpinning has been provided.
- 5.8 Outline retaining wall calculations have been provided however, the parameters used are not consistent with those presented in the BIA and require revisiting.
- 5.9 The Ground Movement Assessment (GMA) has been undertaken using Oasys PDisp and XDisp software. The GMA concludes that the maximum Burland Scale damage category is Category 1 (Very Slight). However, impact to the highways and buried services should be provided and assessment of a two lift underpin construction method should also be provided.
- 5.10 Reference to CampbellReith providing or requesting movement values in the GMA should be removed, as it is not factually accurate.
- 5.11 A movement monitoring strategy during excavation and construction is recommended.
- 5.12 Queries and comments on the BIA are described in Section 4 and Appendix 2. At present, it cannot be confirmed that the BIA complies with the requirements of CPG: Basements and the Principles for Audit set out in the Basement Impact Assessment (BIA) Audit Service Terms of Reference & Audit Process, specifically:
 - The Basement Impact Assessment has not been prepared in accordance with the processes and procedures set out in CPG: Basements.
 - The conclusions of the various documents/details comprising the BIA are not consistent with each other.
 - The conclusions have not been arrived at based on cautious or moderately conservative engineering values/estimates.

Basement Impact Assessment Audit 27 Elizabeth Mews, London NW3 4UH



Appendix 1

Consultation Responses

None

Appendix

Basement Impact Assessment Audit 27 Elizabeth Mews, London NW3 4UH



Appendix 2 Audit Query Tracker



Audit Query Tracker

| Query No | Subject | Query | Status | Date closed out |
|----------|--|---|-----------------------------------|-----------------|
| 1 | Plans | Utility information should be provided. | Open – paragraph 4.18 | |
| 2 | Land stability/ Construction Methodology | The structural report calculations uses different geotechnical parameters to those provided in the BIA. Parameters should be presented and used consistently throughout the submission. | Open – paragraph 4.22 | |
| 3 | Land stability | Number of underpin stages/ lifts must be clearly stated and the ground movement assessments revised accordingly. | Open – paragraph 4.20 and 4.28 | |
| 4 | GMA | Reference to CampbellReith providing or requesting movement values in the GMA should be removed, as it is not factually accurate. | Open – paragraph 4.27 | |
| 5 | Land Stability | Provide confirmation of the impact to the highways and buried services. | Open – paragraph 4.31 | |

Basement Impact Assessment Audit 27 Elizabeth Mews, London NW3 4UH



Appendix 3

Supplementary Supporting Documents

None

Appendix

London

15 Bermondsey Square London SE1 3UN

T: +44 (0)20 7340 1700 E: london@campbellreith.com

Bristol

Unit 5.03 HERE 470 Bath Road Bristol BS4 3AP

T: +44 (0)117 916 1066 E: bristol@campbellreith.com

Birmingham

Chantry House High Street, Coleshill Birmingham B46 3BP

T: +44 (0)1675 467 484 E: birmingham@campbellreith.com

Manchester

10 Chapel Walks Manchester M2 1HL

T: +44 (0)161 819 3060 E: manchester@campbellreith.com

Campbell Reith Hill LLP. Registered in England & Wales. Limited Liability Partnership No OC300082 A list of Members is available at our Registered Office at: 15 Bermondsey Square, London, SE1 3UN VAT No 974 8892 43