







NOTES

 Indicative Site Boundary

-  Poorly matched late 20th Century sashes.
-  Mechanical extract in upper sash
-  Lower sashes in poor condition

