

# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240		Sheet <b>1</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR	Date 09/12/2024		



Living room at staircase level.

01



Typical detail for cabling routes.

02

# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240		Sheet <b>2</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR	Date 09/12/2024		



A number of timbers not regularised.

03



04



# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240		Sheet <b>3</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR	Date 09/12/2024		



Bedroom adjacent to front wall.

05



Tie bar at front wall.

06

# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240	Sheet <b>4</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR		



Floor beam to bedroom at spine wall.

07



Floor beam at spine wall.

08



# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240	Sheet <b>5</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR		



Floor beam jointed into beam at spine wall.

09



Tie bar and galvanised strap at front wall.

10

# Photo Sheet

Project 51 Lambs Conduit St	Job no. 1985/240		Sheet <b>6</b>	<b>Alan Baxter</b> 75 Cowcross Street London EC1M 6EL tel 020 7250 1555 email aba@alanbaxter.co.uk www.alanbaxter.co.uk
	Taken by DR	Date 09/12/2024		



Another non regularised joist.