



Bottom of gutter detail outside Theatre Office window

As Existing

1:5

1:5



KEY TO MATERIALS

- 1 Existing timber clerestorey Window to Store
- 2 Existing brickwork
- 3 Existing lead lined gutter
- 4 Timber furring and boards below lead gutter
- 5 Timber joists below timber boards assumed notched into brickwork
- 6 Existing facing stonework

P01 Issue for Planning			28:01:25 ck	
rev.	description	date	drawn	chkd

client :

UCL

project :

The Slade School of Fine Art
Gower St London WC1E 6BT
External Repairs

drawing title :

Gutter Detail 2
Bottom of gutter outside Theatre Office
As Existing

FulkersBaileyRussell

London | Basingstoke | Brighton | Bristol | Cardiff | Kings Hill | Manchester

proj no : 24 4682

scale:
1: 5 @A3

identifier :

4682-FBR-A1-XX-DR-A-157

status:

S2 (For Information)

rev no:

P.01