

Sample Panel Record for glazed brickwork repairs

**Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ**

Sample Panel Glazed Brickwork repairs

Introduction

The methodology for undertaking the brickwork repairs is detailed in supporting document
'60 Great Queen Street - Methodology Statement'

Sample Panel Record for glazed brickwork repairs

**Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ**

Brickwork Replacement Works

The following is an example of brickwork replacement repair undertaken within the lightwell which is the benchmark for all repairs.



Photo 1. Existing brickwork opened up to investigate corroded steelwork.

Sample Panel Record for glazed brickwork repairs
Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ



Photo 2. Reinstated brickwork repair.

Cathodic Protection installation to Brickwork

Sample Panel Record for glazed brickwork repairs

**Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ**

The following photographs demonstrate how the Cathodic Protection ribbon is installed within the brickwork.

The example is the benchmark for all repairs.



Photo 3. Existing glazed brickwork.

Sample Panel Record for glazed brickwork repairs
Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ



Photo 4. CP ribbon being installed to corner vertical joint.

Sample Panel Record for glazed brickwork repairs
Grand Connaught Rooms Lightwell, Freemasons Hall,
60 Great Queen Street, London, WC2B 5AZ



Photo 5. CP ribbon installed and repointed.