


— 65.00


0 DISTANCE IN METERS

- 55.00 Garage Entrance - 50.00 45.00 m (ABOVE OS DATUM)

Elevation 7



Elevation 9



Elevation 8

LEGEND Street Furniture & Services

 ⊕ Bus Shelter ○ TOP Top of Pipe GATE Gate **⊘** PBOX Phone Box ☐ MHSQ 5.12 Manhole Square © TP Telegraph Pole © BIN Waste Bin ■ FMH 5.12 Foul Manhole * STAY Stay for pole : TL Traffic Light SWMH
5.12 Surface Water MH —— Over Head Wires TRAFCAB Traffic Cabinet ─ wm Water Main
 □ EBOX Electricity Cabinet®RS Road Sign

Natural Features

+ 5.12 Natural Surface ** Tree Coniferous Contour lines Tree Deciduous

+ 5.12	Bottom of Slope	0000 0	Treeline
+ 5.12	Top of Slope	0	Bush
+LAKE 5.12	Lake Line	* TOT 5.12	Top of Tree
+ <u>POND</u> 5.12	Pond Line	攀鞍鞍	Hedge Line
+5.12	River	Ψ SCRUB	Scrub
+ STRM 5.12	Stream	泰蒙泰	Overgrowth

Built Features Internal Survey Roads & Road Markings

Features 4.37 Ceiling Height 233F False Ceiling Height

- Arrows Point Up → Sloping Ceiling

FD Fire Door

FWAY Fair Way
GREE Green

+ 5.12 Surface Change


Murphy Surveys Ltd. Disclaimer


□ TBOX Tee Box


The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as "UTS".

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or

damages suffered by the Client.
The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified







	wn by : MZ, SK ecked by : AOK	Date: 10/12/2013 Date: 10/12/2013	Grid System: OSGB
	•	Revisions	
No.	Date	Description	
Α	10/12/13	First Drawing	
В	22/01/14	Location Plan Added	
С	28/01/14	Elevations 7-9 Included	
	Ham the state of t	THE SURVEY	EUROPEAN GPR ASSOCIATION







9 Devonshire Square Phone: (+44) 020 3178 6644 London EC2M 4YF

www.murphysurveys.co.uk

Pocket Living Oak Grove 28/01/2014 | Scale : 1:100@A1 External Elevations 7-9

MSL8720-E-RevC-03

© Copyright 2014 MURPHY SURVEYS LTD