




Elevation 4



Elevation 6



Elevation 5



LEGEND Street Furniture & Services

 ⊕ Bus Shelter **⊘** PBOX Phone Box ■FOPTIC Fiber Optic

POLE Pole ■ FMH 5.12 Foul Manhole * STAY Stay for pole : TL Traffic Light ■ SWMH
5.12 Surface Water MH —— Over Head Wires ☐ TRFCAB Traffic Cabinet

─ wm Water Main
 □ EBOX Electricity Cabinet®RS Road Sign

+ 5.12 Natural Surface ** Tree Coniferous

Contour lines Tree Deciduous

Natural Features

₊ 5.12	Bottom of Slope	0000	Treeline
+ ^{5.12}	Top of Slope	(3)	Bush
+LAKE 5.12	Lake Line	* TOT 5.12	Top of Tree
+POND 5.12	Pond Line	泰泰泰	Hedge Line
+5.12	River	₩ SCRUB	Scrub
STRM	Ctroom	动物动物	Overmoveth

Built Features Internal Survey Roads & Road Markings **Features**

- Arrows Point Up → Sloping Ceiling

				Λ.	
	Building	S1 <u>. 1888.888</u>	Survey Station	50.02	Floor Level
_	Wall	+ 5.12	Hard Surface	4.37	Ceiling Height
2_	Edge of Road	FL	Floor Level	2.33F	False Ceiling Heigh
2_	Footpath	APEX	Apex Height	BH 3.67	Beam Height
2_	Kerb (bottom)	EAVES	Eaves Height	DH 2.22	Door Height
2_	Kerb, (top)	PARAPET	Parapet Height	F-C 0.27 C-H 3.34	Floor to Cill Cill to Head
CO	Crash Barrier	SOFF	Underside of Soffit	h 0.9	Height
2_	Railwav	a 5 12	Top of Wall Level	A/C	Air Conditioner

FD Fire Door FWAY Fair Way
GREE Green

___ Line of Fence *STPL Step Level

+ 5.12 Surface Change


□ TBOX Tee Box


Murphy Surveys Ltd. Disclaimer The user or recipient of this survey data understands and acknowledges this data may be inaccurate or contain errors or omissions and the user or recipient assumes full responsibility for any risks or damages resulting from, arising from, or in connection with any use of or reliance upon data displayed herein. Although significant care has been exercised to produce surveys that satisfy survey accuracy standards, these surveys are only as accurate as the source data from which they were compiled. Although all reasonable steps have been taken to locate all features visible at the time of the survey, there is no guarantee that all will be shown on the drawing, as some above ground features may have obstructed the survey. Wherever possible, areas unable to be surveyed will be labelled as "UTS".

The Company shall not be liable for any inaccuracy of the data provided beyond the specified scale or accuracy, or for any matters resulting from their use for purposes other than that stated in the Contract. No liability shall attach to the Surveyor in respect of any consequential loss or

damages suffered by the Client.
The Client must promptly notify the Company of any errors in mapping of which it becomes aware. If misleading, inaccurate or otherwise inappropriate information is brought to the Company's attention or the Company itself identifies any such imprecision or error in a survey, it shall use its reasonable endeavours to fix or remove it and if necessary in certain instances, the Company being on notice of any such misleading, inaccurate or otherwise inappropriate information, it will re-conduct the survey and reproduce the data to within the specified

scale or accuracy.





	veyed by : MZ, SK	Date: 09/12/2013	Datum : OSGB
	wn by : MZ, SK	Date: 10/12/2013	Grid System: OSGB
Che	ecked by : AOK	Date: 10/12/2013	
		Revisions	
No.	Date	Description	
Α	10/12/13	First Drawing	
В	22/01/14	Location Plan Added	
С	28/01/14	Elevations 7-9 Included	
	STITUTIONO		EUROPEAN
			CDD
	NEW		upr
	A STATE OF THE STA	THE SURVEY	ASSOCIATION







9 Devonshire Square London EC2M 4YF Phone: (+44) 020 3178 6644 Email:london@murphysurveys.co.uk

www.murphysurveys.co.uk

Pocket Living					
ect :		_			
		Grove			
:	28/01/2014	Scale :	1:100@A1		
criptio	en: External Ele	evation	s 4-6	_	

MSL8720-E-RevC-02

© Copyright 2014 MURPHY SURVEYS LTD