


PHOTOGRAPH 1
Rotten window to be replaced




PHOTOGRAPH 2
Rotten door to be replaced



PHOTOGRAPH 3
Wall in which new opening will be located



PHOTOGRAPH 4
Rotten door to be replaced



Site:	Drawing:	Scale:	Dwg No:
29 GOLDINGTON STREET LONDON NW1 1UE	GROUND FLOOR Elevation of new opening Photographs of external door & window that are to be replaced	1: 50 (@A4)	P294.03
		Date:	Rev:
		Dec 2013	.