

Item No	Ident mark	TYPE			complete box sash	Original	DATE			Usable	CONDITION			recomm	DIMS	Material	comms		
		Upper sash	Lower Sash	Casement			19th C	20th C Early	20thC 21stC		Borderline	Unusable	Previous repair						
563			1					1					1	dispose	440 x 1345 x 45	softwood	missing bottom rail	lead paint	
564				1				1			1			review	440 x 1390 x 53	softwood	opening	rot	replace bottom rail
565			1					1				1		review	440 x 1345 x 45	softwood	opening	lead paint	damage to rails
566	W11			1				1					1	keep	457 x 1136 x 45	softwood	opening	rot	replace bottom rail replace bottom of both stiles
567					1					1	1				1570 x 1135 x 123	softwood	very recent	goes with 0569	
568					1					1	1				1573 x 1135 x 128	softwood	unused		
569				1						1	1				760 x 912 x 40	softwood	very recent	goes with 0567	
570				1						1		1		dispose	1215 x 812 x 35	softwood	not in original position?	never used as a running sa: nailed shut	internal window
571				1				1			1			review	940 x 910 x 39	softwood	replace bottom rail	possible rot in bottom of both stiles	
572		1						1			1			review	838 x 875 x 39	softwood	replace bottom rail	possible rot in bottom of both stiles	
573				1					1		1			review	1094 x 910 x 43	softwood	opening		
574		1							1		1			review	1090 x 883 x 34	softwood	opening	rot	replace bottom rail replace right stile
575				1				1			1		1	review	1095 x 910 x 42	softwood	opening	cut outs	
576		1						1			1			review	1090 x 876 x 35	softwood	opening	damp	replace bottom rail rot
577		1						1			1			review	1088 x 875 x 38	softwood	opening	damp	replace upper rail
578				1				1			1		1	review	1090 x 908 x 47	softwood	opening	damp	losses damaged glazing bars
579				1				1			1		1	review	985 x 1010 x 50	softwood	opening	rot	damp
580		1						1			1			review	985 x 995 x 44	softwood	opening	damp	replace bottom rail rot
581	W2			1				1			1			review	1092 x 910 x 47	softwood	opening	damp	rot damaged glazing bars
582		1						1			1			review	1092 x 874 x 39	softwood	opening	scrappy	damage to glazing l losses
583	W11			1				1					1	review	455 x 1137 x 46	softwood	opening	rot	replace bottom rail replace bottom of both stiles
584				1				1			1			review	363 x 950 x 40	softwood	opening		replace bottom rail replace bottom of both stiles
585	W12?			1				1				1		dispose	1090 x 1374 x 44	softwood	collapsed	rot	damage to glazing bars
586		1						1					1	dispose	1090 x 1348 x 45	softwood	collapsed	rot	missing bottom rail missing glazing bars
587		1						1					1	dispose	1085 x 1350 x 45	softwood	collapsed		replace bottom rail missing glazing bars
588				1				1			1			review	1315 x 1583 x 45	softwood	opening	rot	replace bottom rail
589		1						1			1			review	1315 x 1447 x 45	softwood	opening	arched top	replace bottom rail
590	W8			1				1					1	review	364 x 911 x 32	softwood	opening	rot	replace bottom rail replace bottom of both stiles
591	W8	1						1			1			dispose	365 x 878 x 33	softwood	opening	rot	replace bottom rail replace bottom of both stiles
592	W8			1				1			1			dispose	365 x 910 x 34	softwood	opening	rot	replace bottom rail replace bottom of both stiles
593	W8	1						1			1			dispose	364 x 875 x 35	softwood	opening	rot	replace bottom rail replace bottom of both stiles
594				1				1					1	dispose	990 x 1010 x 44	softwood	opening	rot	replace bottom rail replace bottom of both stiles
595		1						1			1			dispose	933 x 874 x 33	softwood	opening	rot	replace bottom rail
596	W8			1				1			1			review	938 x 920 x 34	softwood	opening	rot	replace bottom rail replace bottom of both stiles
597				1				1			1			review	990 x 1135 x 45	softwood	opening	loose	dismantle remake
598		1						1			1			review	988 x 1105 x 37	softwood	opening	loose	dismantle remake replace bottom rail
599				1				1			1			review	380 x 1135 x 39	softwood	opening		dismantle remake
600				1				1				1		review	381 x 1135 x 38	softwood			
601		1						1				1		review	380 x 1104 x 38	softwood		missing glazing bar	
602				1				1					1	dispose	607 x 1146 x 42	softwood	collapsed	missing bottom rail	rot
603		1						1					1	dispose	607 x 1102 x 45	softwood	opening		dismantle remake
604				1				1			1			review	607 x 1150 x 42	softwood	opening		dismantle remake
605	W11			1				1				1		review	830 x 1103 x 45	softwood	opening	rot	
606	W11			1				1			1		1	review	834 x 1138 x 42	softwood	opening		
607		1						1					1	dispose	988 x 996 x 44	softwood	opening	rot	replace bottom rail replace bottom of b damage to glazing bars
608		1						1			1			dispose	1091 x 1350 x 44	softwood	opening		replace bottom rail
609	W14?			1				1					1	dispose	1092 x 1374 x 45	softwood	opening	rot	replace bottom rail replace glazing bars
610				1				1					1	dispose	1345 x 1145 x 42	softwood	collapsed		
611		1						1					1	dispose	1100				
612					1				1	1			1	dispose	470 x 1000 x 32	softwood	opening	missing bottom rail	
613					1			1	1				1	dispose	330 x 1300 x 35	softwood	opening	replace bottom rail	remake
614					1				1	1				dispose	373 x 1030 x 32	softwood	opening	scrappy	

615	1	1	1	1	dispose	373 x 1025 x 32	softwood	opening	missing bottom rail
616	1	1	1	1	dispose	365 x 1600 x 30	ferrous metal	rusted	