EXISTING FRONT ELEVATION

0 1 5

© Copyright

Copyright of this drawing is retained by AMU Surveys.
Any discrepancies between this drawing and any other information should be reported to AMU Surveys.

Standard Abbreviations (where applicable):

Building Survey		Land Survey	
AB	AIR BRICK	B	BOLLARD
ACU	AIR CONDITIONING UNIT	BB	BELISHA BEACON
AH	ACCESS HATCH	BT	B.T. COVER
AP	ACCESS PANEL	CAM	CAMERA
AV	AIR VALVE	CATV	CABLE TV COVER
BH	BEAM HT	CL	COVER LEVEL
BR	BOILER	ELEC	ELECTRIC COVER
BSL	BEAM SOFFIT LEVEL	EP	ELECTRIC POLE
CB	CUPBOARD	ER	EARTH ROD
CC	CEILING CHANGE	FP	FLAG POLE
CIH	CLEAR INTERNAL HT	FW	FOUL WATER
C-A	CILL TO APEX HT	GU	GULLY
C-H	CILL TO HEAD HT	GV	GAS VALVE
C-S	CILL TO SPRING HT	HYD	FIRE HYDRANT
DB	DOOR BASE HT	IC	INSPECTION COVER
DH	DOOR HEAD HT	IL	INVERT LEVEL
DR	DRAIN	LP	LAMP POST
EXF	EXTRACTOR FAN	MH	MANHOLE
FA	FIRE ALARM	MKR	MARKER POST
F-A	FLOOR TO APEX HT	P	POST
F-C	FLOOR TO CILL HT	PM	PARKING METER
F-H	FLOOR TO HEAD HT	PI	PIPE
F-S	FLOOR TO SPRING HT	RO	RODDING EYE
FL	FLOOR LEVEL	RS	ROAD SIGN
GEA	GROSS EXTERNAL AREA	RWP	RAIN WATER PIPE
GIA	GROSS INTERNAL AREA	SA	SITE AREA
GU	GULLY	SI	SIGN
HT	HEATER	SL	SOFFIT LEVEL
HW	HOT WATER TANK	SV	STOP VALVE
NIA	NET INTERNAL AREA	SVP	SOIL VENT PIPE
NTS	NOT TO SCALE	SW	STORM WATER
RAD	RADIATOR	TF	TOP OF FENCE
RE	RECESS HEAD HEIGHT	TP	TELEGRAPH POLE
RFV	RAISED FLOOR VOID	TW	TOP OF WALL
RL	ROOF LIGHT	UTL	UNABLE TO LOCATE
RSH	ROLLER SHUTTER	UTR	UNABLE TO RAISE
RWP	RAIN WATER PIPE	VP	VENT PIPE
SVP	SOIL VENT PIPE	WM	WATER METER
V	VENT	WT	WATER TAP
WA	WARDROBE		

Symbols (where applicable):

Direction of sloping ceiling

FL 10.00 — FLOOR LEVEL RELATIVE TO DATUM

3.00 — FLOOR TO STRUCTURAL CEILING HT

3.00 — FLOOR TO SUSPENDED CEILING HT

Notes:

The Survey has been computed on an arbitrary grid.

All Levels are in meters and relate to OS datum (No. 196 Regents Park Road, N ANG NW FACE: 38.086m).

Station 1 Value 37.528m

All direction arrows indicate UP unless otherwise stated.

Drainage pipe sizes (where shown) have been gauged from the surface (for safety reasons) and should be regarded as approximate only.

Visible features in the vicinity of any boundaries, as shown on this survey, may not represent the extent of legally conveyed ownership.

Whilst every effort has been made to determine wall materials, no guarantee is given. Materials should be regarded as assumed unless verified by a qualified third party.

Rev	Date	By	Description

AMU Surveys
LAND & MEASURED BUILDING SURVEYS
Office F47 Sabichi House,
5 Wadsworth Road,
Perivale UB6 7JD,
0208 799 7430
www.amusurveys.co.uk
info@amusurveys.co.uk

Client: SOHO HOUSE

Project: 115-117 REGENT'S PARK ROAD LONDON NW1 8UR

Drawing Title: EXISTING FRONT ELEVATION

Date:	Scale:	Surveyor:	Drawn:	Checked:
05/08/2013	1:50@A1	AU	AU	AU

Job No:	Drawing No:	Sheet No:	Rev:
13040	13040-03	03 OF 05	