

## 4 Hampstead Square

### Tree Protection Report – March 2013

The plan of for Tree root protection has now been undertaken, so that materials and damaging activities are excluded from the zone in the garden of Number 4.

The photograph below shows the protection in place.





CHC 26 March 2013