



Photo 1

Self Seeded Ash Tree next to brick garden wall to rear garden of 111 A Chetwynd Road.



Photo 2

Detail of root damage to brick wall and pier from garden of 109 Chetwynd Road.