


A ROOFTOP LOCATION OF LIFT SHAFT OVERRUN/RELOCATED VENT



relocation of existing vent, location of head of shaft overrun



B EXTERNAL VIEW OF LIFT SHAFT LOCATION



external view of lift overrun, curtains to obscure portion of lift shaft seen through existing windows

arts lettres techniques ARCHITECT Arts Lettres Techniques Limited 2012 copyright is retained ©
33A ARLINGTON ROAD LONDON NW1 7ES T: (020) 7383 4778 alan.chandler@member.riba.org
PROJECT CECIL SHARP HOUSE NUMBER CSH 0117 SCALE 1:250
SUBJECT ROOF PHOTOGRAPHS existing REVISION DATE 01/09/12

revisions

