

SAMPLE SUBMITTAL FORM

Works Package	Contractor	Contractor Reference	Date Submitted	
Windows	Red Architectural	R5-SSF-167	19-06-2012	
Location	Reason			
R5 North & West	For Submission & signoff			
Sample Description & Photo		Carillion Comments	Mock up Location	
		Constructed from Schuco FW60+ thermally broken system Refer to PRP elevation drawings (20)E11 to 19 for colour. All curtain walling to level 00 (Ground floor) retail shop fronts and common areas.	Sample held on site	
Carillion Reference		Date Sent		
R5-SSF-167		19-06-2012		
Date Returned		Status Returned	Status Returned	
Comment / Action				
Approved By		Signed (Carillion)		
Name:		Name:		