

The Clockhouse Public House, Leather Lane
London EC1N

Photographs




1. RH side door to remain and be fixed closed



3. Main bar area (unaltered)



5. Kitchen to be female WC facility



2. Site location



4. First floor



6. External stair reconfiguration