



### 2801 - Camden Lock Village Light Pollution Report

**Sources of information:**

- IR47 | 67 | 68 | 70

**Issue No:**

IS4-2801


**Page No:**

11

Lit areas which are visible and not visible from sensitive receptors - Roofs

**Date:**

January 2, 2012



— Site boundary line

- Relevant sensitive receptors
- Lit areas visible (tested)
- Lit areas not visible (part of strategy)

Figure 7: Top view



### 2801 - Camden Lock Village Light Pollution Report

Night-time road closure

Sources of information:

- IR47 | 67 | 68 | 70

Issue No:


IS4-2801

Page No:

12

Date:

January 2, 2012



— Site boundary line

■ Road closed after 8.30pm

Figure 8: Top view



### 2801 - Camden Lock Village Light Pollution Report

Night-time survey readings

Sources of information:

- IR47 | 67 | 68 | 70

Issue No:


IS4-2801

Page No:

13

Date:

January 2, 2012



— Site boundary line

■ Spot reading in Lux

Figure 9: Top view



## 2801 - Camden Lock Village Light Pollution Report

Night time light rendering and overview

Sources of information:

- IR47 | 67 | 68 | 70

Issue No:

IS4-2801

Page No:

14

Date:

January 2, 2012




Figure 10: Night-time render



Figure 11: Falsecolour view