

Photographic Survey

Application for Approval of Details reserved by Condition No.2 of
Listed Building Application with Ref: 2010/4325/L, to

Minerva House,
1-4 North Crescent,
Chenies Street,
London, WC1E 7ER



Minerva House Refurbishment

Photographic Survey
1031/PS Rev - Jan 2012



PH01 - Horizontal crack to central bay of 3rd floor cornice to front elevation

PH02 - Horizontal crack to central bay of 3rd floor cornice to front elevation



Minerva House Refurbishment

Photographic Survey
1031/PS Rev - Jan 2012



PH03 - Horizontal crack to central bay of 3rd floor cornice to front elevation

PH04 - Horizontal crack to central bay of 3rd floor cornice to front elevation



Minerva House Refurbishment

Photographic Survey
1031/PS Rev - Jan 2012



PH05 - Horizontal crack to left hand bay of 3rd floor cornice to front elevation

PH06 - Horizontal crack to left hand bay of 3rd floor cornice to front elevation



Minerva House Refurbishment

Photographic Survey
1031/PS Rev - Jan 2012



PH07 - Spalling concrete lintel to rear elevation

PH08 - Spalling concrete lintel to rear elevation

