


Easter Goods Yard, King's Cross
2007/5228/P

Application in Relation to Condition 5
Crane Base 1, Turntable B and Capstan B

Appendix 4: Crane Base 1 Coping Stone Damage Survey

See Following Report


Crane Base 1: Stone Damage Survey




STONE DAMAGE SURVEY
Nov '11

Plan of Crane Base from Turntable B
1:40 at AS



Key	Photo
D1	 A photograph of a light-colored, textured concrete block. A vertical blue tape with the number '657' is attached to the left side. A red rectangular box highlights a dark, irregularly shaped area on the right side of the block, which appears to be a crack or a hole. The block is resting on a dark surface.
D2	 A photograph of a light-colored, textured concrete block. A horizontal blue tape with the number '3A' is attached to the middle. A red rectangular box highlights a dark, irregularly shaped area on the right side of the block, which appears to be a crack or a hole. The block is resting on a dark surface.

D3	
D4	

D5



D6

