


7



Cracking within ground floor cupboard on Right Party wall

Photos taken  
on 12 July. 2011.



Cracking across dropped beam at junction of rear projection




Junction of Main Structure and Rear Projection



8



Landing - Left party wall at junction of rear projection 1



Landing - Left party wall at junction of rear projection 2



Wall-Ceiling Separation within Rear Bathroom

9



Wall-Ceiling Separation within Rear Bedroom



10

30 September 2011  
Above bathroom door - dropped beam junction  
of rear projection