


PHOTO 1D

SHOWING INTERNAL VIEW OF
EXISTING WINDOW


FLAT 4
42 Belsize Sq.
NW3 4HN
3rd Oct. 2011



PIVOTAL
POINT

NOT DOUBLE
GLAZED, NO
SAFETY GLASS,
NO VENTILATION.

WINDOW POSITIONED
NEXT TO BATH
AND IN FULL VIEW
OF WINDOW IN NEXT
DOOR PROPERTY.
WE WOULD LIKE
FROSTED SAFETY
GLASS IN
NEW WINDOW.



EXISTING WINDOW
SCREWED
CLOSED.

Photo 1D