

Photo 1E

PHOTO 1E - VIEW OF EXISTING WINDOW

NOT TO SAFETY STANDARDS

AND DANGEROUS FOR

BATHROOM SETTING

Existing Window:

Pivot style opening on a horizontal axis.

No ventilation.

Not to regulation standards.

FLAT 4
42 Belsize Sq.
London
NW3 4HN
3rd Oct. 2011




Photo 1E