39 Swinton Street Schedule of Windows, First, Second and Third Floors-Date of Existing Window frames and glazing

First Floor:

Location:

Estimated Age of Windows

Front Window West	1980's
Front Window East	1980's
Rear Window(kitchen)	1980's

Second Floor:

Front Window West	1980's
Front Window East	1980's
Rear Window(dining)	1980's
Rear Window(stair)	1980's

Third Floor:

Front Window West	1980's
Front Window East	1980's
Rear Window	1980's

RECEIVED 2 1 OCT 2010