



Photo No. 1

Front elevation.





Photo No. 2

Rear elevation.





Photo No. 3

Rear garden.



Photo No. 4

Existing brick wall at the rear of the garden.





Photo No. 5

Excavation area at the rear of the garden to uncover the concrete slab, 300 mm below garden level.





Photo No. 6 Trial hole at the rear where concrete slab was discovered.