



Existing opening between rooms to be retained

Blue dotted line denotes non-original partition as shown in drawing PL 04 to be demolished

Removal of high level steel strap subject to engineers details. Engineers drawings to be approved if repair works alter historic structure